
EGNM



415

EGNM

N53 51.96 W001 39.65			LEEDS BRADFORD			681ft AMSL	
Rwy	Dim(m)	Surface	TORA(m)	LDA(m)	Lighting		
14/32	2250x46	Concrete	14-2113	14-1802	Ap Thr Rwy	RCL PAPI 3.5°	
			32-2190	32-1916	Ap Thr Rwy	RCL PAPI 3°	
Take-off:	Rwy	14 from inte	rsection with H	Holding Poin	t E2TORA	\ 1933m	
	Rwy 14 from Rwy 14 thresholdTORA 1801m						
Rwy 14 from intersection with Twy AlphaTORA 1514m							
Rwy 14 from intersection with Twy FoxtrotTORA 1429m							
	Rwy	14 from inter	rsection with 1	wy Mike	TORA	\ 1245m	
Rwy 14 from intersection with Twy LimaTORA 961m							
	Rwy	32 from Rwy	32 threshold		TORA	\ 1916m	
	Rwy	32 from inter	rsection with 1	wy Delta	TOR/	\ 1629m	
	Rwy	32 from inter	rsection with 1	wy Lima	TORA	\ 1115m	

Op hrs: 0700-2300. PPR outside these hours.

Landing Fee: Up to 3 tonnes £6.59 per 0.5 tonne or part.

Hangarage: Limited. Maintenance: Available. Customs: via Handling Agent.

Remarks: Operated by Leeds Bradford Airport Ltd.,

Leeds Bradford Airport, Leeds LS19 7TU.

Flights within the Leeds Bradford CTR/CTA are governed by the regulations applicable to Class 'D' Controlled Airspace.

Pilots operating in the vicinity of, but intending to remain outside Leeds Bradford CAS and maintaining a listening watch on Leeds App freq 134•580 are encouraged to select SSR code 2677. See page 32.

Visiting GA pilots must ensure that they are fully briefed on arrival, departure and taxi procedures prior to using the aerodrome. ATZ entry may be refused, or flights can expect significant delays if unfamiliar with ATC procedures.

Helicopter Operations - see page 418.

CTR/CTA and VRPs - see page opposite and chart at page 419.

Non-radio aircraft & Microlights not accepted.

Aircraft must carry Third party Insurance cover of not less than two million pounds.

Training Flights: A booking slot system in operation— slots must be booked by application to ATC Tel: 0113 3913282. The filing of a flight plan does not constitute a booking to carry out training.

Handling: Handling for all aircraft including those for maintenance mandatory. Suitable handling arrangements required prior to arrival.

Handling Agents:

Northside: Swissport, Tel: 0113 2503251; Radio: 130•500.

Southside: Multiflight, Tel: 0113 2387140/7118, Radio: 131.685.

GA and Business Aviation handling provided on the Southside by Multiflight Ltd and on North side by Servisair.

continued

N53 51.96 W001 39.65	LEEDS BRADFORD	681ft AMS
----------------------	----------------	-----------

VOD/DME EIV

Remarks (continued):

VDD

Visual Reference Points (VRPs)

VNF	VOR/DIVIE FIX
Dewsbury (DBY) N53 41.50 W001 38.10	POL R101°/17nm
Eccup Reservoir (ECP) N53 52.27 W001 32.60	POL R070°/21nm
Harrogate (HGT) N53 59.50 W001 31.60	POL R055°/25nm
Keighley (KLY) N53 52.00 W001 54.60	POL R044°/10nm

Warnings:

Bird hazard - Large flocks of Lapwings on and adjacent to the airfield.

Expect Windshear and turbulence when the surface wind is between 190° and 280° above 20 kt.

Paragliding at Tong within the CTA,195°M/7 nm. Paragliders transit to and from the site from the SW not above 1000ft QNH.

Pilots under VFR/SVFR are requested to avoid this area if possible.

Traffic information will NOT be passed by ATC.

Hang gliding and paragliding takes place on Baildon Moor within the CTR,

265°M/4.2 nm. Hang gliders and paragliders operate within a 1 mile radius of this site, non-radio not above 1500ft QNH.

Pilots under VFR/SVFR are requested to avoid this area if possible.

Traffic information will NOT be passed by ATC.

Hang gliding and paragliding takes place on Ilkley Moor within the CTR,

297°M/6.4 nm. Hang gliders and paragliders operate within a 1 mile radius of this site, non-radio not above 1500ft QNH.

Pilots under VFR/SVFR are requested to avoid this area if possible. Traffic information will NOT be passed by ATC.

Restaurant: Restaurant, buffet and bar.

Fuel: Multiflight Ltd.

Jet A1 by BP/Conoco -Northside

Tel: 0871 288 3285 Admin
Tel: 0113 391 3282 ATC

or Multiflight -Southside. Tel: 0113 391 3231 Airside & Safety Unit

Fax: 0113 250 5426 Admin (09-1700 Mon-Fri) Fax: 0113 391 0870 ATC

Email: airside.operations@lba.co.uk (Airside Operations Unit)

atc@lba.co.uk (ATC)
Website: www.lbia.co.uk

HELICOPTER OPERATIONS

a. Arrival Procedures: ATC will allocate either a direct approach, or a circuit join based on the runway in use, dependant on the prevailing traffic conditions.

b. Direct Approach:

- Helicopters are to approach the aerodrome from the northeast or southwest remaining well clear of the approach and climb out to Rwy 14/32;
- ii. Helicopters will be requested to report approaching the aerodrome boundary to await further instructions;
- iii. Direct arrivals from the northeast are to obtain clearance to cross Rwy 14/32 prior to crossing the aerodrome boundary and be prepared to hold, or orbit at the boundary if requested. When cleared to cross the runway helicopters are to arrange their flight to cross the runway as expeditiously as possible direct to the allocated Helicopter Aiming Point (HAP) avoiding overflying any parked or taxing aircraft;
- iv. Direct arrivals from the southwest are to report approaching the aerodrome boundary for onward clearance. When cleared to do so arrivals shall route direct to the allocated HAP ensuring that they remain well to the south of Rwy 32 at all times. The south side taxiway runway holding points may be used as a reference point as the point to remain south of when approaching the HAP from the south.
 - If, due to the surface wind conditions it is required to cross Runway 32 to enable a turn into wind for arrival this should be requested on first contact with the Leeds Tower Controller

c. Circuit Based Approach:

 Under certain traffic conditions helicopters may be given a standard circuit join for the runway in use. On turning final the helicopter is to break directly for the allocated HAP prior to reaching the runway threshold.

d. Taxi Instructions:

 ATC will issue an instruction to air taxi from the HAP to the relevant parking apron.

e. Departure Procedures:

- i. Helicopters will be given clearance to lift from the apron and air taxi to the allocated HAP. When cleared for take-off, South, or Westbound departures shall depart ensuring that they remain well to the south of Rwy 32 at all times. If surface wind conditions dictate that a lift into wind requires a runway crossing this should be requested prior to taxi;
- ii. Departures to the east or north shall, when cleared to do so cross the runway as expeditiously as possible on track the relevant VRP, ensuring that the departure track does not overfly parked or taxing aircraft.

