


N53 47-81 W000 05-50

GARTON FIELD

39 ft AMSL

9-9 nm NE of Kingston upon Hull

OTR 113.90 006 5-5**SAFETYCOM 135-475. Humberside App/RAD 119-130 (LARS)**

Rwy	Dim(m)	Surface	TORA(m)	LDA(m)	Lighting
10/28	560x14	Grass	Unlicensed	Nil	
Rwy 10 Thld displaced by 90 m					

Op hrs: Strictly PPR. SR-SS. (PPR essential by telephone for briefing)**Landing Fee:** Nil.**Customs:** Nil.**Hangarage:** Nil.**Maintenance:** Nil.**Remarks:** Operated by Mr Matthew Butler, Dairy farm, Church Street, Adlbrough, Hull, HU11 4RN.

Visiting acft welcome at pilot's own risk.

Visual aids to location: White hangar at the East end of the strip.

Windssocks South of the runway

Warnings: 30 ft agl power lines cross the Rwy 10 approach 500 m from thld.

Crops grown to the Northern edge of the runway.

Low hedge runs along the Southern edge of the runway.

10ft hedge and trees on the Western airfield boundary.

Gas venting site 1.5 nm to the North.

Fuel: Nil.**Tel:** 01964 527400 (PPR)**Mob:** 07836 672900**Email:** mjbutlerplanthireltd@btinternet.com